

Authored Date	18/03/2024	
Doc No.	IATSB003024	
Title	Roof Bar Cover - Replace	
Affected Vehicle(s)	Grenadier	PF00001 -
This Technical Service Bulletin (TSB) should only apply to vehicles that demonstrate the described issue below.		

Reason for this document

Issue: An issue has been identified on a small percentage of the affected vehicles where water run downs the rear side window.

Cause: Design Issue.

Action: Follow the procedure below.

Workshop Procedure.

Roof Bar Cover - Replace

Operation	SRO	Repair Time
Replace	XTSBRBCR001	0.1

Parts

Part Number	Description	Qty
GRA-7E21-030210	Roof Rail Side Cover	1
GRA-0000-004470	Washer M6	6

Procedure

1	Remove and discard the Roof Bar Cover. Refer to: TOPIC_000000994 Roof Side Cover Front Left (Remove for Access and Install) TOPIC_0000003020 Roof Side Cover Front Right (Remove for Access and Install) TOPIC_0000003019 Roof Side Cover Rear Left (Remove for Access and Install) TOPIC_0000003021 Roof Side Cover Rear Right (Remove for Access and Install)
2	<p>Note: New washers must be installed when fitting the Roof Side Cover.</p> Install the New Roof Bar Cover. Refer to: TOPIC_000000994 Roof Side Cover Front Left (Remove for Access and Install) TOPIC_0000003020 Roof Side Cover Front Right (Remove for Access and Install) TOPIC_0000003019 Roof Side Cover Rear Left (Remove for Access and Install) TOPIC_0000003021 Roof Side Cover Rear Right (Remove for Access and Install)
3	Release the Vehicle. <i>Parts: GRA-7E21-030210 Roof Rail Side Cover. Quantity: 1</i> <i>GRA-0000-004470 Washer M6. Quantity:6</i>

Change History

Reference No.	Date	Description
IATSB003024	18/03/2024	First release

