



# NOOSA



## mazda

**Noosaville**  
 148 Eumundi-Noosa Rd  
 Noosaville QLD 4566  
 Telephone: 07 5430 6100  
 Facsimile: 07 5474 0955  
 Email: info@noosamazda.com.au  
 Web: www.noosamazda.com.au

Service TAX Invoice		Page 1 of 2		1		Doc #: IEC SN141770	
Customer No. 124022	Customer Name & Address Andrew & Jennifer Kilby 8 Earnshaw Street			Advisor Rick Hofer	918	Colour	Team Mazda Se
Doc. Date 03/01/24	Golden Beach QLD 4551			Year / Make / Model 23/INEOS/Grenadier		Tag No.	
Reg. No. 857IU8				Model No. GDB86B85DGGLQ1	Carline INEOS		Eng./Trans.
Stock No. I1026	Purchase Order No. Driver			Contract No.	Contract Name	Contract Exp. Kms	Exp. Date
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT		Home Phone	Business Phone	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 28/11/23
Vehicle ID. SC6GM1DB3PF004606		Engine No. 50987185B57D30		Date & Time Promised 02/01/24 07:00pm	Time Received 08:15am	Quote Price	Air Pwr Turb
Mobile Phone 0404-654082	Mazda Stock# 5312836		Customer Email Address andrew@yidneyrocks.com.au				

Labour	Operation	Description	Units	Amount
Job# 1	11MZELECT2	ELECTRICAL BODY	Tech(s): 904	143.50
<b>IAMWO002203 Software Update</b> Carried out software update as required.				
Job# 2	11MZZZZZZ	ELECTRICAL BODY	Tech(s): 904	143.50
<b>IAMWO002193 Alternator Cable Position</b> Checked/confirmed alternator cable routing. All ok no further action required				
Job# 3	25MZZZZZZ	STEERING	Tech(s): 904	143.50
<b>IAMWO002310 Longitudinal Arm Torque</b> Carried out arm re-torque as required.				
Job# 4	07MZZZZZZ	BODY COMPONENTS	Tech(s): 888	No Charge
<b>Report on no power at NATO plug</b> Tested power at Nato plug. No power until ignition switch on/roof console switch on and vehicle in Park/ Neutral or Drive. Also will power off when travelling above 80kph. For different use Ineos suggests either rewire power source or add anderson plug.				
Job# 5	07MZZZZZZA	BODY COMPONENTS	Tech(s): 904	143.50
<b>Rectify water gathering between both door seals at left front door</b> Ineos are finding a resolution. Ineos advised adding a small relief at lower point of outer seat until permanent fix is found. Carried out temp repair as per Ineos.				
Job# 6	07MZZZZZZB	BODY COMPONENTS	Tech(s): 888	No Charge
<b>Pls move Cargo barrier to front position if possible.</b> Not possible due to designed to only be used in rearmost position. Fitting in any other position may be unsafe/void warranty.				
<b>Total - Labour</b>				<b>574.00</b>





# NOOSA



## mazda

**Noosaville**  
 148 Eumundi-Noosa Rd  
 Noosaville QLD 4566  
 Telephone: 07 5430 6100  
 Facsimile: 07 5474 0955  
 Email: info@noosamazda.com.au  
 Web: www.noosamazda.com.au

**Service TAX Invoice** Page 2 of 2 1 Doc #: **IECSN141770**

Customer No. 124022	Customer Name & Address <b>Andrew &amp; Jennifer Kilby</b> 8 Earnshaw Street			Advisor <b>Rick Hofer</b> 918	Colour	Team <b>Mazda Se</b>
Doc. Date 03/01/24	Golden Beach QLD 4551			Year / Make / Model 23/INEOS/Grenadier		Tag No.
Reg. No. 857IU8				Model No. GDB86B85DGGLQ01	Carline INEOS	Eng./Trans.
Stock No. I1026	Contract No.			Chassis No.	Kilometres 2557	Prod. Date 01/01/01
Purchase Order No.	Driver	Contract Name		Contract Exp. Kms	Exp. Date	Orig. Del. Date 28/11/23
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 28/11/23
	Vehicle ID. SC6GM1DB3PF004606	Engine No. 50987185B57D30	Date & Time Promised 02/01/24 07:00pm	Time Received 08:15am	Quote Price	Warr. Exp. Date
						Air Pwr Turb

**Total Labour** 574.00  
**Total Parts** 0.00  
**Total POL** 0.00  
**Total Sublet** 0.00  
**Total Misc** 0.00

**Total Tax** 57.40  
**Total Invoice** 631.40

**INCLUDING GST**